


<b>Technical Data - Clutch</b>		Year	88 - 91
		Model	Z 1
		Unit	
<b>21 21...Clutch</b>			
Deviation at diaphragm spring	mm		0,6
Min. liner thickness	mm		7,5
Max. lateral runout	mm		0,5





Service-Information BMW Automobile



Service-Information BMW Automobile



Service-Information BMW Automobile

**All Service Informations are saved in german language, please find them in the german manual.**